




Photograph No.: 27	Orientation: Southeast
TDD Number: S05-0808-003	Date: November 13, 2008
Photographer: K. Campbell, START	Site Name: Carter Color Coat Removal Site
Location: Detroit, Wayne County, Michigan	
Subject: U.S. EPA contractors sweeping the dry solids on the fifth floor of the building.	



Photograph No.: 28	Orientation: West
TDD Number: S05-0808-003	Date: November 19, 2008
Photographer: K. Campbell, START	Site Name: Carter Color Coat Removal Site
Location: Detroit, Wayne County, Michigan	
Subject: U.S. EPA contractors stabilizing solids on site for disposal.	



Photograph No.: 29	Orientation: East
TDD Number: S05-0808-003	Date: November 21, 2008
Photographer: K. Campbell, START	Site Name: Carter Color Coat Removal Site
Location: Detroit, Wayne County, Michigan	
Subject: Sump found in truck ramp area filled with unknown liquid.	



Photograph No.: 30	Orientation: East
TDD Number: S05-0808-003	Date: November 21, 2008
Photographer: K. Campbell, START	Site Name: Carter Color Coat Removal Site
Location: Detroit, Wayne County, Michigan	
Subject: U.S. EPA contractors sweeping dry solids on the fourth floor of the building.	



Photograph No.: 31	Orientation: North
TDD Number: S05-0808-003	Date: January 5, 2009
Photographer: K. Campbell, START	Site Name: Carter Color Coat Removal Site
Location: Detroit, Wayne County, Michigan	
Subject: Disposal of hazardous waste water.	



Photograph No.: 32	Orientation: East
TDD Number: S05-0808-003	Date: January 5, 2009
Photographer: K. Campbell, START	Site Name: Carter Color Coat Removal Site
Location: Detroit, Wayne County, Michigan	
Subject: Disposal of non-hazardous waste water from the truck ramp.	